

VEHICLE INSPECTION REPORT

KU18DYY

MERCEDES-BENZ ANTOS 2545

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	01/05/2018	VIN	WDB96302020212324	Rear Suspension	Air
Year	2018	Body Style	Fridge Box	Rear Doors	Barn
Mileage	480,589 Km Warranted	Cab Type	DAY CAB	Tail Lift	Column
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	6x2		

FRIGOBLOCK UNIT, STANDBY PLUG, SINGLE EVAP, SEPARATOR, REAR LIFT, SURROUND CAMERA SYSTEM, GARDNER DENVER HYDRAPAK

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Air conditioning

Photos





